



# Sangamon River Watershed, Illinois (Lake Decatur, Illinois)

U.S. ARMY CORPS OF ENGINEERS

BUILDING STRONG ®

## Location

Sangamon River Watershed upstream of Lake Decatur, Illinois

## State(s)

IL

## Congressional District(s)

IL-3

## Status

Authorized, but not funded. Project will most likely be addressed as a component of Illinois River Basin Restoration Section 519, WRDA 2000 authority.

## Description

The Sangamon River watershed is located in central Illinois and is a major tributary to the Illinois Waterway, which passes through Lake Decatur. Lake Decatur, the water supply source for the city of Decatur, is experiencing water quality problems and ecosystem degradation. Sedimentation and high nitrate levels are affecting the water quality. This study would focus on the restoration of water quality and methods to control and remediate nutrient enriched sediments in the portion of the Sangamon River, which feeds into Lake Decatur.

## Summarized Project Costs

Federal Cost	\$665,000
Non-Federal Cost	\$565,000
Total Cost	\$1,230,000
Allocations through FY 2008	\$0
Allocations for FY 2009	\$0
Budget Request for FY 2010	\$0
Balance to Complete after FY 2010	\$665,000

## Major Work Item (This Fiscal Year)

**FY 2016:** None. Likely to be addressed under Section 519 WRDA 2000 authority.

## Major Work Item (Next Fiscal Year)

**FY 2017:** None. Likely to be addressed under Section 519 WRDA 2000 authority.

## Authority Details

This study is authorized by Section 503 of the Water Resources Development Act 1996, PL 104-303, as amended by Section 552 of the Water Resources Development Act of 2000.



# **Sangamon River Watershed, Illinois (Lake Decatur, Illinois)**

---

**U.S. ARMY CORPS OF ENGINEERS**

**BUILDING STRONG®**

**Point of Contact:** Program Manager, Project Management Branch

**Phone:** (309) 794-5399

**Email:** cemvr-pm-web@usace.army.mil

---

**U.S. ARMY CORPS OF ENGINEERS - ROCK ISLAND DISTRICT**

CLOCK TOWER BLDG. - P.O. BOX 2004 - ROCK ISLAND, IL 61204-2004

[www.mvr.usace.army.mil](http://www.mvr.usace.army.mil)